


ギヤ比	段数	ナ入力厚	+	ギヤ部	+	間座 t	=	L1	ナ入力寸法
1/7.5~1/10	2段	4	+	12.6	+	7	=	23.6	24
1/12.5~1/30	3段	4	+	15.1	+	7	=	26.1	24
1/40~1/100	4段	4	+	17.6	+	7	=	28.6	24
1/120~370	5段	4	+	20.1	+	7	=	31.1	29
1/400~1000	6段	4	+	22.6	+	7	=	33.6	29

SCALE=1:1.25

NS-37SG-□-24NKSS5BA1

ギヤ比	L1	ギヤ比	L1
1/7.5~1/10	23.6	1/120~1/370	31.1
1/12.5~1/30	26.1	1/400~1/1000	33.6
1/40~1/100	28.6		



SCALE=4:5